TYX CORPORATION

Productivity Enhancement Systems

PAWS Studio
Release Notes

Version 1.37.15
December 7, 2009

Table of contents

1   Paws Developer's Studio

Version 1.37.15
Release date: December 7, 2009

1.1   Critical Items

1.2   Known Limitations

1.3   Enhancements

1.4   Problem Reports

2   Run Time System

Version 1.37.15
Release date: December 7, 2009

2.1   Critical Items

2.2   Known Limitations

2.3   Enhancements

2.4   Problem Reports

2.4.1   PR 09119

The Switch Server process and the Nam process in the WRTS allow the DatVM to be manipulated. However, before the Switch Server process can manipulate the DatVM, the WRTS is required to explicitly close its own handle of the DatVM. This has been fixed.