

August 2, 2013

## **Dear Valued Customer:**

As part of our ongoing product lifecycle management, the Racal Instruments<sup>™</sup>1277 ARINC-608 switching system has transitioned to an "obsolete/unsupported" status. The increasing shortage of replacement components coupled with the retirement of employees who have worked with this product has made it difficult to continue supporting this line. The status change applies to "1277" part numbers listed below herein and is effective immediately.

We want to thank you for your business and are committed to providing you with the highest quality products and services. If you have any questions, please contact us.

Racal Instruments<sup>™</sup>1277 ARINC-608 switching system "obsolete/unsupported" detail, July 2013

MODEL	DESCRIPTION	PART No.
1277	21-Slot ARINC 608A Chassis (Includes Opt.65)	407054
1277-S-1775	Typical 21-Slot ARINC 608A Chassis w/Rear Bulkhead Connectors, wired	404984
1277-1	Power Switching with Switched Feed through	401997
1277-1-004	Power Switching w/Feed through in Group A	401997-004
1277-2	Resource Distributor with Switched Feed through	401998
1277-3	Bus Matrix Module	401999
1277-4	Source Switching Module	405000
1277-5A	96-Channel Discrete Digital Module	405046
1277-6	Resource Interface Feed through Cable	407113
1277-7	Coax Module ARINC Version	405060-001
1277-8	ARINC 629 Feed through Cable	407109
1262-77A #	VXI Chassis with ARINC 608/Hinged Receiver (order 1260-77 separately w/Opt.05)	407123
1262-77A/5 #	Complete Integrated System, 5-Slot Sub-Chassis, 1262-77A, 1260-77, Opt.05	407126
1262-77A/10#	Complete Integrated System (1262-77A, 1260-77, & Opt.10)	407124
1260-77	1277 Card Intelligent Controller	407077
1277-10	Power Switching Module	401997-003
1277-20	Resource Distributor Module	405051
1277-540A	1 GHz Coaxial (No splitters)	405060-002
1277-540B	1 GHz Coaxial (3 Splitters)	405060-003
1277-540C	1 GHz Coaxial (6 Splitters)	405060-004