

PAWS Studio Release Notes

Version 1.43.0 Jan 3, 2019

Table of contents

1	Paws L	Developer's Studio	3
	1.1 Cri	tical Items	3
	1.1.1	PAWS and WRTS Flexera licensing software has been updated	
	1.2 Kn	own Limitations	3
	1.2.1	No known limitations addressed in this release	
	1.3 En	hancements	3
	1.3.1	No enhancements addressed in this release	
	14 Pr	oblem Reports	
	1.4.1	No problem reports addressed in this release	
2	Dun Ti	me System	
_		•	
		tical Items	4
	2.1.1	PAWS and WRTS Flexera licensing software has been updated	
		own Limitations	4
	2.2.1	No known limitations addressed in this release	4
		hancements	4
	2.3.1	No enhancements addressed in this release	4
	2.4 Pro	oblem Reports	4
	2.4.1	LicMgrCfg.exe failed to load the user's checkout sequence from registry (TaskID 1890)	4
3	Paws (Compilers All Subsets	6
		tical Items	_
	3.1.1	No critical items addressed in this release	
	3.2 Kn		
	3.2.1	No known limitations addressed in this release	
	3.3 En		
	3.3.1	hancements No enhancements addressed in this release	0 6
	3.4 Pro	No problem reports addressed in this release	
4	Paws C	Compilers CASS Subset	7
	4.1 Cri	tical Items	7
	4.1.1	No critical items addressed in this release	7
	4.2 Kn	own Limitations	7
	4.2.1	No known limitations addressed in this release	7
	4.3 En	hancements	7
	4.3.1	No enhancements addressed in this release	7
	4.4 Pro	oblem Reports	7
	441	No problem reports addressed in this release	, 7

1 Paws Developer's Studio



Version 1.43.0

Release date: Jan 3, 2019

1.1 Critical Items

1.1.1 PAWS and WRTS Flexera licensing software has been updated

PAWS Studio and WRTS licensing has been upgraded with the Flexera package version 11.16.1.0 in order to provide up-to-date support for latest Windows Operating Systems.

1.2 Known Limitations

1.2.1 No known limitations addressed in this release

No known limitations.

1.3 Enhancements

1.3.1 No enhancements addressed in this release

No enhancements.

1.4 Problem Reports

1.4.1 No problem reports addressed in this release

No problem reports.

2 Run Time System



Version 1.43.0

Release date: Jan 3, 2019

2.1 Critical Items

2.1.1 PAWS and WRTS Flexera licensing software has been updated

PAWS Studio and WRTS licensing has been upgraded with the Flexera package version 11.16.1.0 in order to provide up-to-date support for latest Windows Operating Systems.

2.2 Known Limitations

2.2.1 No known limitations addressed in this release

No known limitations.

2.3 Enhancements


2.3.1 No enhancements addressed in this release

No enhancements.

2.4 Problem Reports

2.4.1 <u>LicMgrCfg.exe failed to load the user's checkout sequence from registry (TaskID 1890)</u>

This application is located in C:\usr\tyx\FlexLM folder. Previously, the application failed to display the current checkout sequence in the list control below



As a result of this error there had been situations when inactive / old floating license servers could have delayed a straight forward node-lock license granting for up to 3 seconds per feature ID. There were other situations when the operator could not reliably control where the floating licenses are consumed from when more floating licensing servers were configured in the network.

Now that the Licensing Checkout Sequence is visible, the operator can manage it. Unwanted floating licensing servers can be easily identified and deleted.

3 Paws Compilers All Subsets



Version 1.43.0

Release date: Jan 3, 2019

3.1 Critical Items

3.1.1 No critical items addressed in this release

No critical items

3.2 Known Limitations

3.2.1 No known limitations addressed in this release

No known limitations

3.3 Enhancements

3.3.1 No enhancements addressed in this release

No enhancements

3.4 Problem Reports

3.4.1 No problem reports addressed in this release

No problem reports

4 Paws Compilers CASS Subset



Version 1.43.0

Release date: Jan 3, 2019

4.1 Critical Items

4.1.1 No critical items addressed in this release

No critical items

4.2 Known Limitations

4.2.1 No known limitations addressed in this release

No known limitations

4.3 Enhancements

4.3.1 No enhancements addressed in this release

No enhancements

4.4 Problem Reports

4.4.1 No problem reports addressed in this release

No problem reports