



Number / Rev: OP08014 / J	PECO PO Requirements – Raw Materials	Approved by: Swenson
Issue Date: 26AUG19		Prepared by: Schelert

1.0 Purpose

This document defines PECO-Astronics (PECO) purchased material flow-down requirements. Additional specifications may also apply and will be documented on the purchase order; all requirements must be complied with fully.

2.0 General Notes

- 2.1 Supplier is required to flow down applicable standards and customer requirements to vendors for purchased product, material, and special processes.
- 2.2 Anomalies (non-conformances) or changes in processing which deviate from first article approval must be reported to PECO before shipment of product or as soon as deviations are discovered.
- 2.3 The quality system of each supplier may be subject to periodic remote or on-site audits by PECO, its customers, and/or regulatory agencies, including the Federal Aviation Administration (FAA).
- 2.4 Supplier must implement appropriate action to correct recurring or repetitive non-conformances.
- 2.5 Supplier shall not relocate manufacturing facilities, subcontract work, or make any change to manufacturing equipment, process, or material without written notification and acknowledgement from PECO. Supplier will flow down this requirement to its subtiers.

3.0 QUALITY SYSTEM REQUIREMENTS

- 3.1 Inspection System, General – The supplier shall maintain an inspection system that complies with MIL-I-45208, AS9100, and/or ISO 9001, and is acceptable to PECO. The inspection system shall ensure that all product complies to purchase order or referenced specifications.
- 3.2 Inspection System, Boeing-Designed Products – Where applicable, the supplier shall maintain an inspection system that complies with Boeing D6-82479: (1) AS9100; or (2) AS9003. Acceptance sampling shall conform to Boeing D1-8007.
- 3.3 Special processors – Where noted on the PO, suppliers and sub-tier suppliers of special processes performed on products and materials for use in Boeing products must be on the Boeing Document D1-4426 “Approved Process Sources” for heat treat, non-destructive testing, chemical processing, welding, brazing, material testing, shot peening, & composite mfg.

Number / Rev: OP08014 / J	PECO PO Requirements – Raw Materials	Approved by: Swenson
Issue Date: 26AUG19		Prepared by: Schelert

- 3.4 Nadcap Accreditation – Boeing D1-4426 suppliers and sub-tier suppliers must be Nadcap accredited for heat treat, non-destructive testing, chemical processing, welding, brazing, material testing, shot peening, & composite mfg.
- 3.5 Digital Data – Boeing D6-51991 suppliers, and sub-tier suppliers, must have an approved system to control digital data, where applicable.
- 3.6 Calibration System Requirements – The supplier shall maintain a calibration system in accordance with ANSI-Z540.3 or ISO-10012-1. This system shall control the accuracy of all devices used to measure, gage, test, inspect or otherwise examine items to verify acceptability of materials or services in performance of this purchase order.
- 3.7 Documentation – Record Retention - Data that provides objective evidence of implementation shall be retained at Supplier's facility for a calendar year plus ten years. Retention periods begin at the end of the purchase order or contract. Storage methods must prevent, or minimize, deterioration and loss to records. Specific customer requirements for longer retention periods may apply and will be flowed down in PO notes.
- 3.8 Change in Quality Management Representative – PECO shall be promptly notified of any changes in the Management Representative with assigned responsibility and authority for the quality system.
- 3.9 Change in Quality System Procedures - PECO shall be immediately notified, in writing, of any changes to the quality system that may affect inspection, conformity, or airworthiness of the product.
- 3.10 Tooling – Boeing tooling document D33200 is applicable for the receipt and/or fabrication of Boeing or Boeing customer-owned accountable tools.
- 3.11 Acceptance Authority Media (AAM) - Use of AAM must be considered as a personal warranty of compliance and conformity. The supplier shall ensure that the use of AAM is clearly defined within its QMS.

4.0 INSPECTION REQUIREMENTS

- 4.1 Source Surveillance – All items specified by the purchase order are subject to surveillance by our Quality Assurance staff or that of our customers. Suppliers shall provide all the necessary inspection equipment needed to substantiate complete conformance of materials or services and a suitable area for this inspection. This may include a review of the suppliers' inspection system, procedures, and quality or test records.

5.0 FOREIGN OBJECT DAMAGE/DEBRIS

Number / Rev: OP08014 / J	PECO PO Requirements – Raw Materials	Approved by: Swenson
Issue Date: 26AUG19		Prepared by: Schelert

5.1 Supplier shall make provision for the prevention, detection and removal of foreign objects per AS9146. Such provisions shall establish specific requirements and procedures for the control of Foreign Object Debris/Damage, and shall have controls which are being implemented to ensure cleanliness of work areas. These requirements and procedures must include the following aspects: a) adequate control of tools and consumables on the shop floor; b) product and process design guidelines to reduce/prevent FOD; c) adequate training of all personnel; d) housekeeping and maintenance procedures designed to reduce/prevent FOD.

6.0 CERTIFICATION AND LABELING REQUIREMENTS

- 6.1 Certification of Conformance (COC) – Each shipment shall be accompanied by one legible copy of a COC which includes a statement that attests to the supplier’s conformance with all the requirements of the purchase order. The COC will contain at a minimum:
- 6.1.1 Conformance Statement.
 - 6.1.2 PECO Purchase Order Number.
 - 6.1.3 PECO Part Number.
 - 6.1.4 Part Revision.
 - 6.1.5 Supplier’s Shipping Document Number.
 - 6.1.6 Serial Numbers, Lot Numbers and Heat or Batch Number, as applicable.
- 6.2 Raw Material, Chemical and Physical Test Reports – Each shipment shall be accompanied by one legible copy of a certified test report listing the actual results of tests (mill or independent lab certifications) for all materials supplied. These reports must agree in every respect with the raw material, chemical and physical requirements of the applicable specification(s).
- 6.3 Requirements for Domestic Specialty Metals – When specified on the purchase order, each shipment containing specialty metals must be compliant with DFARS 252.225-7009, Preference for Domestic Specialty Metals.
- 6.4 Ozone-Depleting Substances - Supplier shall label products which contain or are manufactured with ozone-depleting substances in the manner and to the extent required by 42 U.S.C. 7671j (b), (c), and (d) and 40 CFR Part 82, Subpart E, as applicable:
- “Warning - Contains * _____, a substance(s) which harm(s) public health and environment by destroying ozone in the upper atmosphere;” OR
 - “Warning - Manufactured with * _____, a substance(s) which harm(s) public health and environment by destroying ozone in the upper atmosphere.”

Number / Rev: OP08014 / J	PECO PO Requirements – Raw Materials	Approved by: Swenson
Issue Date: 26AUG19		Prepared by: Schelert

* *Supplier shall insert the name of the substance(s) where indicated.*

6.4.1 "Ozone-depleting substance," as used in this note, means any substance the Environmental Protection Agency designates in 40 CFR Part 82 as--

(1) Class I, including, but not limited to, chlorofluorocarbons, halons, carbon tetrachloride, and methyl chloroform; or

(2) Class II, including, but not limited to hydrochlorofluorocarbons.

6.4.2 This note shall be included in the supplier's direct supply contracts and flowed to the sub-tier supply chain. For the purposes of this note, 'supply chain' shall mean supplier's direct and indirect suppliers performing value-added activity on the products and services provided under this agreement.

7.0 NOTIFICATION OF ESCAPEMENT (NOE) PROCESS:

7.1 If supplier determines that goods or materials already delivered to PECO contain or are likely to contain a nonconformance, supplier shall notify PECO in writing with all reasonable haste. Written notification shall include:

7.1.1 The affected process or product number(s), including PECO part number

7.1.2 Description of the nonconforming condition and the relevant engineering requirement

7.1.3 Scope of the nonconformance: Purchase Order numbers, quantities, and shipping dates

7.1.4 Suspect or affected lot numbers, date codes, or other part identifiers

7.2 The supplier shall notify PECO procurement and Supplier Quality engineering personnel of the nonconformance.

This requirement shall be flowed down to all subtiers used in the performance of PECO purchase orders.

8.0 EXPORT COMPLIANCE AND CLASSIFICATION

8.1 Export Compliance - Supplier will comply with United States export control and sanctions laws, regulations, and orders applicable to the export and re-export of goods, software, technology, or technical data ("Items") or services, including without limitation the Export Administration Regulations ("EAR"), International Traffic in Arms Regulations ("ITAR"), and regulations

Number / Rev: OP08014 / J	PECO PO Requirements – Raw Materials	Approved by: Swenson
Issue Date: 26AUG19		Prepared by: Schekert

and orders administered by the Treasury Department's Office of Foreign Assets Control (collectively, "Export Control Laws").

- 8.2 Export Classification - Supplier shall, upon request, provide PECO with the Export Control Classification Numbers ("ECCNs") of any items purchased by PECO.

9.0 REVISION HISTORY

Rev #	Name	ECN #	Change Date	Character of Change
A				Initial release of Operating Procedure.
B-E				Not captured
G	Schekert	16489	9OCT18	To supplier quality flowdowns, add section 7.0 Notification Of Escapement process, update NADCAP references to current stylization as Nadcap;
H	Schekert	17615		Add section 6.4 Ozone-depleting substances; add section 8 Export Compliance and Classification. Update FOD specification reference.