

Supplemental Type Certificate

Number SA02372AK

This certificate issued to One Sky Aviation
3811 Aircraft Drive
Anchorage, Alaska 99502

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations

Original Product - Type Certificate Number: A24CE
Make: Hawker Beechcraft
Model: B200/B300 Series Aircraft

Description of Type Design Change: Installation of the Max-Viz® Enhanced Vision System (EVS) Model-1500 on Hawker Beechcraft B200/B300 series aircraft equipped with a Rockwell Collins ProLine-21 Adaptive Flight Display (AFD) having the video capability upgrade, p/n 822-1753-354 and Primary Flight Display (PFD), p/n 822-1084-354 in accordance with One Sky Aviation Master Data List, Doc. No. 20 11 00, dated March 10, 2010, or later FAA approved revision.

Limitations and Conditions:

1. Compatibility of the design change with previously approved modifications must be determined by the installer.
2. FAA approved One Sky Aviation Airplane Flight Manual Supplement, Doc. No. 32 11 04, Rev. IR, dated March 10, 2010, or later FAA approved revision, is a required part of this modification.
3. Instructions for Continued Airworthiness, Doc. No. 33 11, Rev. IR, dated March 10, 2010, or later FAA accepted revision.
4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.


Date of application: November 30, 2009

Date of issuance: May 19, 2010

Date reissued:

Date amended:

By direction of the Administrator


(Signature)

August A. Asay
Manager, Anchorage Aircraft Certification Office

(Title)



Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.